

Untitled

BRS L44 8138 460/\$.ccls. USPAT; US-PGPUB; EPO; JPO; DERWENT 2004/08/09 07:58
BRS L45 498 44 and (thresh\$3 and rotor) USPAT; US-PGPUB; EPO; JPO; DERWENT 2004/08/09 07:58
BRS L46 250 45 and ((thresh\$3 and rotor) with axial) USPAT; US-PGPUB; EPO; JPO; DERWENT 2004/08/09 07:58
BRS L47 221 45 and ((thresh\$3 with rotor) with axial) USPAT; US-PGPUB; EPO; JPO ; DERWENT 2004/08/09 07:58
BRS L48 118 47 and (rotor with (element or protrusion or rib)) USPAT; US-PGPUB; EPO; JPO; DERWENT 2004/08/09 07:59
BRS L49 22 ("0005229" | "0376552" | "0376652" | "0640939" | "1790663" | "2301536" | "3036486" | "3555790" | "3762537" | "3964492" | "4170235" | "4209024" | "4398607" | "4399825" | "4478226" | "4492237" | "4972665" | "5112279" | "5342239" | "5368522" | "6092750" | "6503143" | "2002/0016192" | "2002/0103015").PN. USPAT2004/08/09 08:00
BRS L50 12 ("3669122" | "3670739" | "3848609" | "3916912" | "4078571" | "4208858" | "4669489" | "4889517" | "5112279" | "5688170" | "5833533" | "6083102").PN. USPAT2004/08/09 08:01
BRS L51 14 ("3481343" | "3664100" | "3848609" | "4148323" | "4178943" | "4230130" | "4291709" | "4440179" | "4964838" | "5145462" | "5344367" | "5364306" | "5387153" | "5413531").PN. USPAT2004/08/09 08:01
BRS L52 5 4964838.URPN. USPAT2004/08/09 08:02
BRS L53 11 ("1776396" | "2050631" | "2363632" | "4124032" | "4348855" | "4362168" | "4611605" | "4875891" | "5078646" | "5112279" | "5145462").PN. USPAT2004/08/09 08:03
BRS L54 14 4362168.URPN. USPAT2004/08/09 08:04
BRS L55 15 ("3927679" | "4266393" | "4505279" | "4889517" | "4946419" | "4986794" | "5035675" | "5083977" | "5125871" | "5145462" | "5192245" | "5368522" | "5387153" | "5413531" | "5489239").PN. USPAT2004/08/09 08:06
BRS L56 11 ("2266806" | "3410271" | "3481344" | "3512533" | "3664100" | "3669121" | "3982548" | "4148323" | "4178943" | "4250897" | "4362168").PN. USPAT2004/08/09 08:07